



LEDLima DALI


Item Code	CCT	kg
542005000500	3000K	2.5 kg
542005000600	4000K	2.5 kg
542005000700	3000K	3.1 kg
542005000800	4000K	3.1 kg
542005001300	3000K	2.5 kg
542005001400	4000K	2.5 kg
542005001500	3000K	3.1 kg
542005001600	4000K	3.1 kg
599006009000*	/	0.09 kg

* Accessories should be purchased separately.















Model	L (mm)	W (mm)	H (mm)
LED Lima-L12-15W-U19-DALI	1200	70	75
LED Lima-L15-18W-U19-DALI	1500	70	75
LED Lima-L12-30W-U22-DALI	1200	70	75
LED Lima-L15-36W-U22-DALI	1500	70	75












Suspending









*Suspension Kit sold separately.



Ceiling



Unmount luminaire




In case of damage to the wire, it has to be replaced only by the manufacturer, distributor or by an expert, to avoid risks.

Caution: Any operation on LED module is forbidden while power-on.


Zur Vermeidung von Risiken müssen defekte Leitungen ausschließlich vom Hersteller, Inverkehrbringer oder Fachmann ausgetauscht werden.

Achtung: In Betrieb ist keine Arbeit am LED-Modul erlaubt.



For non-user replaceable light sources.

The light source contained in this luminaire shall only be replaced by the manufacturer or his service agent or a similar qualified person.



Suzhou Opple Lighting Co., Ltd.
215200
East Side, Fenyang Road,
Fenhu Economic Development Zone,
Wujiang City, Jiangsu Province,
P.R.China

OPPLE Lighting B.V.
Materiaalweg 6-6A
5681 RJ Best
The Netherlands
service@opple.com
www.opple.com